

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**





FIG. 1





**FIG. 3**




FIG. A

101-103




Fig. 5




Fig. 6






FIG. 7




**FIG. 8**

84




SIP

80




MEGACO

82



M  
A  
N  
A  
G  
E  
M  
E  
N  
T  
/  
C  
O  
R  
B  
A  
/  
V  
X  
M  
L

FIG. 9



**FIG. 10**

1100

## High-Level Architecture Millennium Management System




Fig. 11

1200





FIG. 12



**FIG. 13**





FIG. 1A

# Transit / Transmit Buffer Arch



# RPR Frame Format




FIG. 16

## Grooming/Alternate Routing

- Grooming by RF carrier or technology (e.g. cdma2000)
- Grooming by Service Provider




FIG 17

## Straight Talk Service, Priority Access Service




FIG. 18